

7014



ADVANCED PERFORMANCE
AUTOMOTIVE, INC.
 6784 Mid Cities Ave.
 BELTSVILLE, MARYLAND 20705
 (301) 595-9540

DATE PROMISED: 5-18-98 AM
 DATE WRITTEN BY: [Signature]
 ORDER NUMBER: 5-18-98
 CUSTOMER'S ORDER NO. [Blank]

NAME: Jeff Pleas
 ADDRESS: 5031 Berwyn Rd, Beltsville, MD 20710
 CITY: Beltsville, STATE: MD, ZIP: 20710
 HOME PHONE: 301 982-7402
 BUSINESS PHONE: [Blank]
 CALL WHEN READY: YES NO
 MILEAGE: 10,415
 MECHANIC/TECHNICIAN: [Blank]
 SERIAL NO./VIN: [Redacted]
 TRMS: V8
 SERVICE REQUEST/DESCRIPTION OF WORK: [Redacted]

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	AMOUNT
1	10 SW330 oil	1.50
1	1M81 oil filter	7.12
52	SAV30 oil	70.95
1	MT34 Battery - Delco	18.00
3	Box 360 Brake lining	6.00
2	E-71 wiper	3.00
2	Ben 33597 Cam W/Lag	8.00
1	MTV W55R	25.95
1	Ben 140182 Brake Drum (see)	8.00
1	Ben Fluid	2.07
1	Ben 18052 Wheel and (see)	305.00
1	500 Grease fuel tank	5.50
1	MOB 1670694 Fuel tank g/h/his	30.00
1	KR2 wiper	6.95
1	202 oil filter	1.80
1	Fuel tank float	8.90
1	1M81 fuel tank 038018/grommet	4.90
1	STKR 10632 fuel tank cap	5.00
1	Brake Bleed	5.00
TOTAL PARTS		653.07

CUSTOMER'S RIGHTS (State of Maryland)

- The customer may request a written estimate for repairs which cost in excess of \$50.
- The customer may not be charged for any amount ten (10) percent in excess of the written estimate without his consent.
- The customer is entitled to the return of any replaced parts except when parts are required to be returned to the manufacturer under a warranty agreement.
- Repairs not originally authorized by the customer may not be charged to the customer without the customer's consent.
- All repairs guaranteed 90 days or 4000 miles.

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control.

SIGNATURE: [Blank] SAVE OLD PARTS: YES NO

Notes:
 - Battery not working. Replaced with new one.
 - Air filter replaced. Fuel filter replaced.
 - Oil change. Wiper blades replaced.
 - Brake pads replaced. Brake fluid topped up.
 - Grease applied to wheel bearings.
 - Fuel tank grommet replaced.
 - Fuel tank cap replaced.
 - Brake bleed performed.
 - Total labor: 525.00
 - Total parts: 653.07
 - Total subject: 1178.07
 - Tax: 32.65
 - Total: 1210.72

PARTS	LABOR	TOTAL	TOTAL LABOR	TOTAL PARTS	TOTAL SUBJECT	TAX	TOTAL
653.07	525.00	1178.07	525.00	653.07	1178.07	32.65	1210.72

ESTIMATED COSTS: 653.07
 AUTHORIZED BY: [Signature]
 DATE: [Blank]
 TIME: [Blank]
 CALLED BY: [Blank]
 PHONE: [Blank]

EPA / WASTE DISPOSAL: [Blank]
 GAS OIL AND GREASE: 10.00

301-595-9544

Status: 8/14/98

Cornett

- * New rear brake line
- * New wheel cylinders (Rear)
- * New brake shoes
- * Resurface the Drum
- * Replace 1 of the Drum (couldn't get true)
- * Battery
- * Wheel Stubs (Replace a couple)
- * carburetor overhaul
- * change oil
 - * compression test - w to good
 - * cylinder leakage
- Bottom end is good
- * Add a pump to AC system

→ needs new gas tank \$280

→ new sport ~~lock~~ nuts

→ new lock set

→ replace rear tires with same as front tires

→ new leaf springs

→ replace all shocks


→ lower control arm bushing

→ Replace gear box

→ transmission leaks

→ head rebuild

→ new cam shaft



Advanced Performance Automotive Inc.

①

6784 Mid Cities Ave.
Beltsville, MD 20705
(301) 959-9540
545

JEFF KLINE 68 CORONA

TOTALS (P/L)

- ① INITIAL CHECK-OUT ^{COMPLETE} INSPECTION incl COMPRESSION + CYL LEAK-DOWN TESTS -- 160
 ↳ ADJUST REQUIRED TEMPORARILY INSTALL 2.6 GALLON FUEL CELL TO ALLOW CLEAN FUEL
 ↳ CLEAN + ADJUST IGNITION POINTS
 - ② REPLACE BATTERY (INTERSTATE - MT 34 - 60 MONTH MEGATRON) --- 95
 - ③ RUN ENGINE + CHANGE OIL --- 21
 - ④ REPLACE BRAKE LINE TUBING TO REAR (FROM PROPORTIONING VALVE TO REAR FLEX HOSE) } 265 P/L
 TEST + REPLACE REAR WHEEL CYCLES }
 REPLACE REAR BRAKE SHOES, MACHINE DRUMS (NEW DRUM) } 265 P/L
 - ⑤ REMOVE FUEL TANK FOR (SUBJECT) TANK DIAGNOSIS BY RADIATOR SHOP = TANK NOT GOOD
 - ⑥ REPLACE WITH NEW TANK + FILTERS } 305
 ↳ 15
 - ⑦ REPLACE FUEL PUMP --- 90
 - ⑧ CHECK A/C SYS ADD R-12 + TEST OPERATION --- 90
- * TOTAL OF WORK DONE UP TO THIS POINT (APPROXIMATE) →
- ~~_____~~
~~_____~~
~~_____~~
- \$1266.00

WORK STILL NEEDED:

NEXT PAGE



2

Advanced Performance Automotive Inc.

6784 Mid Cities Ave.
Beltsville, MD 20705
(301) 988-9540
Fax - 301-595-5322

REPAIRS STILL NEEDED!

- ✓ ① FRONT BRAKES - CONDITION NEEDS RE-ASSESSMENT (PULLS TO RIGHT)
(POSSIBLE WHEEL CYLINDER PROBLEM) (100-200?)
- ✓ ② 2 NEW REAR TIRES - DUNLOP GT@ P235/60R14 - \$7/ea 175
- ✓ ③ FRONT SUSPENSION: LOWER CONTROL ARM BUSHINGS (65) (POLY) 300
 - FRONT SHOCK (K4B) 80/ea 120
 P/S GEAR BOX ASSY (LEAKS) 265 400
 130. 59
- ✓ ④ REAR SUSPENSION: FEA
 SHOCKS (K4B) - \$80/ea
 REAR LEAF SPRING BUSHINGS
 OR
 NEW SPRINGS (BUSH. INCL) \$240/ea 250
 SHOCKLE BUSHINGS \$60/ea 630
- ✓ ⑤ ENGINE: * ENGINE RUNS WELL NOW + FIRES ON ALL 8 CYLINDERS (BUT HAS INTERMITTENT TAPPING FROM LIFTERS)
 - R+R CYLINDER HEADS + SEND TO MACHINE SHOP FOR O/SHAUL VALVE JOB
 + INSTALL HARDENED VALVE SEATS FOR UNWEARDED FACE COMPATIBILITY 1650.00
 - NEW CAM + LIFTER SET + TIMING CHAIN ASSEMBLY
 (CAN UPGRADE FOR MILD PERFORMANCE IMPROVEMENT WITH 4-BBL CARB)
- ✓ ⑥ CARB → OPTIM 2 BBL?
 OR
 REPLACE INTAKE CARB + CONVERT TO 4BBL? 200 OR
 EASY IF HEADS ARE DONE INTAKE (WILL BE OFF!) 350
 2000 OPTIM 2 BBL OR
 350 CONVERT TO 4 BBL
 Go with the 4 BBL 575